

Production Control – Hold Option

Shop Bill of Material items can be placed on hold by placing the entire drawing on hold or by placing an individual shipping assembly on hold.

To place an entire drawing on hold, select the No option at Released for Fab when entering a new drawing or when editing a drawing. This will place all items in all sequences on hold for the entire drawing. To release the hold, select the Yes option at Released for Fab.

To place a shipping assembly on hold, while displaying the shop bill of material in the editor, highlight the shipping assembly then click the Place 'On Hold' button. This will place the shipping piece and all attached detail pieces on hold. An on hold piece can be released using the Release Hold button while the shipping assembly is highlighted.

An "on hold" item will not be added to a cutting list. It is suggested that you use the "Cut Tracking" option if placing individual pieces on hold otherwise there is not an easy way to add the released item to a cutting list if the balance of the drawing has been previously added to a cutting batch.